EQC ENFORCEMENT REPORT BOARD OF HEALTH AND ENVIRONMENTAL CONTROL AUGUST 11, 2005

BUREAU OF LAND AND WASTE MANAGEMENT

UST Enforcement

1) <u>Order Type and Number</u>: Administrative Order 04-0443-UST

Order Date: March 30, 2005

Respondent: Wilson Creek Logging & Timber

Co., Inc.

<u>Facility</u>: Forks Country Store <u>Location/Mailing Address</u>: 6830 Hwy 187 South

Iva, SC 29655

County: Anderson

<u>Previous Orders:</u> AO 03-01357-UST (\$3,000)

Permit/ID Number: 18592

Violations Cited: UST Control Regulations, R.61-92,

§280.93(a); R.61-92, §280.110(c).

<u>Summary</u>: Wilson Creek Logging & Timber, Company, Inc. owns and operates one underground storage tank located at 6830 Highway 187 South in Iva, South Carolina. The Respondent has violated the South Carolina Underground Storage Tank Control Regulations as follows: failure to demonstrate financial responsibility and failure to supply financial responsibility documentation to the Department upon request.

Action: The Department issued an Administrative Order with a civil penalty of four thousand eight hundred dollars (\$4,800.00) when it became clear that the owner/operator did not intend to enter into a Consent Order or come into compliance by providing the financial responsibility documentation. The Administrative Order was not appealed.

Hazardous Waste Enforcement

2) <u>Order Type and Number</u>: Consent Order 05-12-HW

Order Date: June 21, 2005

Respondent: Tidewater Transfer Company, Inc. Facility: Tidewater Transfer Company, Inc.

<u>Location/Mailing Address</u>: 6174 Highway 70 West Kinston, N.C. 28502

<u>County</u>: Dorchester

Previous Orders: None

Permit/ID Number: NCD 003 458 643

<u>Violations Cited</u>: The South Carolina Hazardous Waste Management Act §44-56-130(2) and the South Carolina Hazardous Waste Management Regulations 61-79.263.10(g)

<u>Summary</u>: Tidewater Transfer Company, Inc. (Respondent), located in Kinston, North Carolina, is a hazardous waste transporter. The Respondent has violated the Hazardous Waste Management Regulations as follows: failure to obtain a permit from the Department prior to transporting hazardous waste in the State of South Carolina.

Action: The Respondent has agreed to: ensure compliance with the requirements applicable to Hazardous Waste Transporters included in 25 S.C. Regs. 61-79.263; and, pay a civil penalty in the amount of two hundred fifty dollars (\$250.00).

3) Order Type and Number: Consent Order 05-13-HW

Order Date: June 21, 2005

<u>Respondent:</u> Fukoku South Carolina, Inc.

<u>Facility:</u> Fukoku South Carolina, Inc.

<u>Location/Mailing Address:</u> 325 Hunter Industrial Park Road

Laurens, S.C. 29360

<u>County</u>: Laurens <u>Previous Orders</u>: None

Permit/ID Number: SCR 000 764 985

Violations Cited: The South Carolina Hazardous Waste Management Act §44-56-130(2) and the South Carolina Hazardous Waste Management Regulations 61-79.262.34(a)(2), R.61-79.262.34(c)(1)(ii), R.61-79.262.34(d)(5)(ii), R.61-79.262.44(b), R.61-79.265.15(d), R.61-79.265.31, R.61-79.265.173(a)(c)(d), and R.61-79.265.174

Summary: Fukoku South Carolina, Inc. (Respondent), located in Laurens, South Carolina, manufactures rubber and plastic products for the automotive industry. The Respondent has violated the Hazardous Waste Management Regulations as follows: failure to label containers holding hazardous waste with an accumulation start date; failure to mark containers of hazardous waste either with the words "Hazardous Waste" or with other words that identify the contents of the container; failure to post the names and the phone numbers for the emergency coordinators, the location of emergency equipment, and the phone number for the fire department next to the telephone; failure to declare generator status annually on or before January 31; failure to record hazardous waste inspections in an inspection log or summary; failure to maintain and operate the facility to minimize the possibility of any unplanned or sudden releases to the air, soil or surface water; failure to close all containers holding hazardous waste except when necessary to add or remove waste; failure to label containers of hazardous waste with the words "Hazardous Waste – federal laws prohibit

improper disposal;" failure to label containers of hazardous waste with the appropriate EPA Hazardous Waste Number(s); and, failure to inspect hazardous waste containers weekly.

Action: The Respondent has agreed to: ensure that all containers of hazardous waste are managed in accordance with R.61-79.262.34 and R.61-79.265 Subpart I – Use and Management of Containers; ensure that weekly inspections are recorded in an inspection log or summary; ensure that the facility operates and complies with the requirements of R.61-79.265 Subpart C – Preparedness and Prevention; ensure that all emergency information is posted next to the telephone; declare generator status annually on or before January 31; and, pay a civil penalty in the amount of thirteen thousand, five hundred dollars (\$13,500.00). The penalty will be paid in four (4) payments.

Solid Waste Enforcement

4) <u>Order Type and Number</u>: Consent Order 05-04-RW

Order Date: June 23, 2005

Respondent: Entergy Nuclear Northeast

Facility: Indian Point 2, L.L.C.

Location/Mailing Address: 450 Broadway

Buchanan, NY 10511-0308

County: Buchanan, NY

Previous Orders: None

Permit/ID Number: 0019-31-05-X

<u>Violations Cited</u>: South Carolina Radioactive Waste Transportation and Disposal Act of 1976 (Act), Transportation of Radioactive Waste Regulation 61-83 (Regulation), Section 1.2; S.C. Radioactive Material License # 097 (License), Amendment # 48,

Condition 61.

<u>Summary</u>: Entergy Nuclear Northeast/Indian Point 2, L.L.C., a nuclear power plant, (Company) failed to package a shipment of radioactive waste to the Chem-Nuclear disposal facility in Barnwell, South Carolina, in a manner that would prevent the release of radioactive waste into the shipping container. This constitutes a violation of the Regulation and the License.

Action: The Company agreed to submit corrective action measures to the Department and to pay a civil penalty of one thousand dollars (\$1,000.00) by no later than July 29, 2005. The civil penalty has been paid.

BUREAU OF WATER

Drinking Water Enforcement

5) <u>Order Type and Number:</u> Consent Order 05-056-DW

Order Date: June 3, 2005

Respondent: Kingston Cove Owners Assoc., Inc. Facility: Kingston Cove Swimming Pool

Location/Mailing Address: 11 Kingston Cove

Hilton Head Island, S.C. 29928

<u>County</u>: Beaufort <u>Previous Orders</u>: None Permit/ID Number: 07-177-B

Violations Cited: S.C. Code Ann. Regs. 61-51(I)(1),

S.C. Code Ann § 44-55-2340 (A),

<u>Summary</u>: Kingston Cove Owners Assoc., Inc. (Respondent) is responsible for the operation and maintenance of a public swimming pool. The Respondent has violated the Public Swimming Pool Regulations as follows: failure to submit the required Change Order Request for decking repairs prior to beginning the work.

Action: The Respondent has agreed to: operate and maintain the public swimming pool in accordance with all applicable State laws and regulations and pay a civil penalty in the amount of one hundred fifty dollars (\$150.00). The civil penalty has been paid.

6) <u>Order Type and Number</u>: Consent Order 05-065-DW

Order Date: June 3, 2005
Respondent: **Donald Curles**

Facility: Milhouse Rentals Public Water

System (PWS)

<u>Location/Mailing Address</u>: 406 Zion Church Rd.

Orangeburg, S.C. 29115

<u>County</u>: Orangeburg

<u>Previous Orders:</u> None Permit/ID Number: 3850002

<u>Violations Cited</u>: S.C. Code Ann. Regs. 61-58.7

<u>Summary</u>: Donald Curles (Respondent) d/b/a Milhouse Rentals is responsible for the operation and maintenance of a PWS. The Respondent has violated the State Primary Drinking Water Regulations as follows: failure to properly operate and maintain the PWS.

Action: The Respondent has agreed to: operate and maintain the PWS in accordance with all applicable State and Federal laws and regulations; correct all deficiencies from the 2002 and 2004 Sanitary Surveys or disconnect the system; and pay a **stipulated penalty** in the amount of four thousand dollars **(\$4,000.00)** if he fails to meet any requirement of this Order.

7) Order Type and Number: Consent Order 05-068-DW

Order Date: June 16, 2005
Respondent: Samuel Byson Jr.

Facility: Whale Branch Mobile Home Park

(MHP)

Location/Mailing Address: 49 Seabrook Rd.

Seabrook, S.C. 29940

County:BeaufortPrevious Orders:NonePermit/ID Number:0760071

Violations Cited: S.C. Code Ann. Regs. 61-58.7

(E)(1), S.C. Code Ann §§ 44-55-40 (D), and 44-55-90 (B)

<u>Summary</u>: Samuel Byson Jr. (Respondent) d/b/a Whale Branch MHP is responsible for the operation and maintenance of a PWS. The Respondent has violated the State Primary Drinking Water Regulations as follows: failure to properly operate and maintain the PWS and failure to have a licensed distribution operator.

Action: The Respondent has agreed to: operate and maintain the PWS in accordance with all applicable State and Federal laws and regulations; correct all deficiencies from the January 19, 2005 Sanitary Survey; and pay a **stipulated penalty** in the amount of three thousand six hundred dollars (\$3,600.00) if he fails to meet any requirement of this Order.

8) Order Type and Number: Consent Order 05-072-DW

Order Date: June 22, 2005

Respondent: Town of Branchville Facility: Town of Branchville

Location/Mailing Address: P.O. Box 85

Branchville, S.C. 29432

<u>County:</u> Orangeburg

<u>Previous Orders:</u> 05-004-DW (\$2,800); 01-073-W

(\$5,600); 03-175-W (AO \$2,000);

04-093-DW (\$400)

Permit ID/Number: 3810005

Violations Cited: S.C. Code Ann. Regs. 61-58.11(H),

S.C. Code Ann. §§ 44-55-90, 49-5-90(A), 49-5-120

<u>Summary:</u> The Town of Branchville (Respondent) is responsible for the operation and maintenance of a PWS. The Respondent has violated the State Primary Drinking Water Regulations as follows: failure to conduct lead and copper monitoring for 2 consecutive monitoring periods and failure to submit a Water Use Report for 2004.

Action: The Respondent has agreed to: operate and maintain the PWS in accordance with all applicable State and Federal laws and regulations; submit public notice for failure to monitor for lead and copper; conduct lead and copper monitoring by September 30, 2005; and pay a civil penalty in the amount of one thousand six hundred eighty dollars (\$1,680.00)

9) Order Type and Number: Consent Order 05-074-DW

Order Date: June 27, 2005

Respondent: Lady's Island Country Club, LLC

<u>Facility</u>: Lady's Island Country Club <u>Location/Mailing Address</u>: 139 Francis Marion Circle

Beaufort, S.C. 29902

County: Beaufort

<u>Previous Orders</u>: 04-119-DW (\$800)

Permit/ID Number: 07GC017

Violations Cited: S.C. Code Ann. §§ 49-5-120(C),

49-5-100(A), 49-5-90(A)

<u>Summary</u>: Lady's Island Country Club, LLC (Respondent) owns and is responsible for the operation and maintenance of a permitted groundwater withdrawal system located at Lady's Island Country Club. The Respondent has violated the Groundwater Use and Reporting Act as follows: failure to apply for and obtain a Permit to Construct for an irrigation well in a designated capacity use area; failure to submit the Water Use Report form; and exceedance of permitted groundwater withdrawal limits during the 2004 monitoring period.

Action: The Respondent has agreed to: operate and maintain the groundwater wells in accordance with all applicable State and Federal laws and regulations; have the unpermitted well properly abandoned by a licensed well driller and submit a well log close-out form; install hour meters or totalizing flow meters on all groundwater sources used for golf course irrigation and keep a monthly log of withdrawals for the wells; secure all wells not currently in use with properly fitted caps; and pay a civil penalty in the amount of two thousand three hundred eighty dollars (\$2,380.00).

Water Pollution Enforcement

10) Order Type and Number: Consent Order 05-064-W

Order Date: June 3, 2005

Respondent: Harbor Gate Co-Owners Council,

Inc.

Facility: Harbor Gate Condominiums

Wastewater Treatment Facility

(WWTF)

Location/Mailing Address: P.O. Box 650

Anderson, S.C. 29622-0650

County:AndersonPrevious Orders:NonePermit/ID Number:SC0021849

<u>Violations Cited</u>: S.C. Code Ann. § 48-1-110(d) (Supp.2004), 24 S.C. Ann. Regs. 61-9.122.47(e) and 61-9.122.41(j)(3)

(Supp. 2004)

<u>Summary</u>: Harbor Gate Co-Owners Council, Incorporated (Respondent) owns and is responsible for the proper operation and maintenance of a WWTF serving the residents of the Harbor Gate Condominium complex located on Highway #24 adjacent to double bridges on Lake Hartwell. The Respondent has violated the Pollution Control Act and associated regulations as follows: failure to submit plans, specifications and an administratively complete application for a permit to construct upgrades necessary to insure compliance with more stringent effluent discharge limits for ammonia-nitrogen (NH₃-N) and total residual chlorine (TRC) and failure to submit administratively complete discharge monitoring reports (DMRs) for the December 2003, January 2004 and June 2004 monitoring periods.

Action: The Respondent has agreed to: submit a preliminary engineering report (PER) addressing the elimination of the discharge by connecting to Anderson County. The PER must also include a letter of acceptance from Anderson County agreeing to accept the flow from the Respondent's WWTF, an administratively complete closure plan, and a schedule for the construction of all appurtenances required to eliminate the discharge. The schedule, upon Department approval, shall be incorporated into and become an enforceable part of the Order. The Department has **suspended** a penalty in the amount of two thousand eight hundred dollars (\$2,800.00) that will be due and payable should the Respondent fail to meet any requirement of this Order.

11) Order Type and Number: Consent Order 05-067-W

Order Date: June 3, 2005

Respondent: SCDOT and Morgan Corporation

<u>Facility</u>: USC-Spartanburg <u>Location/Mailing Address</u>: P.O. Box 191

Columbia, S.C. 29202

County: Spartanburg

<u>Previous Orders:</u> 03-203-W (\$11,200), 04-178-W

(\$1,000), 05-028-W (\$9,800)

Permit/ID Number: SCR107580

<u>Violations Cited</u>: 24 S.C. Code Ann. Regs. 61-

9.122.41(a) and (e)(1) (Supp. 2004).

<u>Summary</u>: South Carolina Department of Transportation (SCDOT) and Morgan Corporation (Respondents) are responsible for the construction activities at the new University of South Carolina (USC)-Spartanburg North Access Road Project (Site). The Respondent has violated the Water Pollution Control Permit Regulations as follows: failure to operate and maintain all sediment and erosion control measures as required.

Action: The Respondent has agreed to: submit a report completed by a South Carolina Registered Professional Engineer certifying that all sediment and erosion control devices are installed and functioning properly as specified by the approved sediment and erosion control plan and pay a civil penalty in the amount of two thousand eight hundred dollars (\$2,800.00).

12) Order Type and Number: Consent Order 05-069-W

Order Date: June 22, 2005

Respondent: Aiken County Public Schools
Facility: Mossy Creek Elementary School

<u>Location/Mailing Address</u>: 1000 Brookhaven Drive

Aiken, S.C. 29803

County: Aiken

<u>Previous Orders</u>: 03-064-W (\$4,200)

Permit/ID Number: SCR107362

Violations Cited: S.C. Code Ann. § 48-1-90(a)(1987),

24 S.C. Ann. Regs. 61-9.122.26(b)(14)(X) and 122.41(a)(Supp. 2004)

<u>Summary</u>: Aiken County Public Schools (Respondent) owns and is responsible for development and construction activity at the Mossy Creek Elementary School (Site) at the N.E. corner of Five Notch Road and Scott Drive. The Respondent has violated the Pollution Control Act and associated regulations as follows: failure to comply with the requirements of the permit to provide adequate sediment and erosion controls and discharged sediment into waters of the State.

Action: The Respondent has agreed to: submit a report completed by a South Carolina Registered Professional Engineer, certifying that implementation of the necessary storm water and sediment control devices have been installed and are functioning properly and pay a civil penalty in the amount of eleven thousand two hundred dollars (\$11,200.00).

13) Order Type and Number: Consent Order 05-070-W

Order Date: June 27, 2005

Respondent: Mohawk Industries, Inc.

<u>Facility</u>: Ulmer Plant <u>Location/Mailing Address</u>: P.O. Box 98

Ulmer, S.C. 29849

County:AllendalePrevious Orders:NonePermit/ID Number:SC0004073

Violations Cited: S.C. Code Ann.§ 48-1-110(d) and 24

S.C. Code Ann. Regs. 61-9.122.41(d) (Supp. 2004)

<u>Summary</u>: Mohawk Industries, Inc./Ulmer Plant (Respondent) is responsible for the operation and maintenance of a WWTF serving its textile manufacturing facility. The Respondent has violated the Pollution Control Act and associated regulations as follows: failure to comply with the effluent limits for fecal coliform.

Action: The Respondent has agreed to: comply with all applicable State and Federal regulations; repair any control devices upon becoming aware of the disrepair; and pay a civil penalty in the amount of four thousand two hundred dollars (\$4,200.00). The civil penalty has been paid.

14) <u>Order Type and Number</u>: Emergency Order 05-073-W

Order Date: June 23, 2005

Respondent: River Pines Water System, Inc.
Facility: Woodforest Subdivision WWTF

<u>Location/Mailing Address</u>: P.O. Box 22023

Charleston, S.C. 29413

<u>County</u>: York

Previous Orders: 05-063-W (\$35,000)

Permit/ID Number: SC0035661

<u>Violations Cited</u>:
S.C. Code Ann. §§ 48-1-90, 48-1-110(d) (Supp. 2004), 24 S.C. Code Ann. Regs. 61-9.122.41 (a) and (e) (Supp. 204), 61-46.1 (g)(1976), 61-56.III (A)(1976) and S.C. Code of Laws § 44-1-140 (2002)

<u>Summary</u>: River Pines Water System, Inc. (Respondent) owns and operates a WWTF and wastewater collection system (WWCS) serving the residences in the Woodforest Subdivision. The Respondent has violated the Pollution Control Act and the Water Pollution Control Permit Regulations as follows: operating the facility without a S.C. certified operator; did not have an S.C. approved laboratory to analyze all permitted requirements; no chlorine was at the facility for the disinfection of the effluent; and discharged untreated wastewater into the receiving stream at the subdivision.

Action: This Emergency Order (EO) was issued because of the imminent threat to human health and the environment. The EO required the Respondent to immediately hire a S.C. certified operator of appropriate grade, deliver to the Department a notarized statement from the hired operator that a satisfactory financial relationship had been entered into; and to begin and continue to properly operate and maintain its WWTF and WWCS in accordance with NPDES Permit and all applicable State and Federal regulations.

15) Order Type and Number: Consent Order 05-078-W

Order Date: June 28, 2005

Respondent: Hallmark, Inc. of Rock Hill Facility: Hallmark Glenn Subdivision

<u>Location/Mailing Address</u>: 2430 Ridgeway Lane

Rock Hill, S.C. 29732

<u>County</u>: York Previous Orders: None

 Permit/ID Number:
 SCR100000 (Cert# SCR104209)

 Violations Cited:
 S.C. Code Ann. § 48-1-110(d)

 (Supp. 2004) and 24 S.C. Code Ann. Regs. 61-9.122.41(a) and (e) (Supp.

2004)

<u>Summary</u>: Hallmark, Inc. of Rock Hill (Respondent) owns and is responsible for the proper operation and maintenance of a permanent storm water retention basin serving the Hallmark Glenn Subdivision. The Respondent has violated the Pollution Control Act and Water Pollution Control Permit Regulations as follows: failed to properly operate and maintain the storm water retention basin.

Action: The Respondent has agreed to: comply with all applicable State and Federal regulations and pay a civil penalty in the amount of six thousand eight hundred dollars (\$6,800.00) in quarterly installments.

BUREAU OF AIR QUALITY

16) Order Type and Number: Consent Order 05-029-A

Order Date: June 20, 2005
Respondent: Holcim (US) Inc.
Facility: Holcim (US) Inc.

Location/Mailing Address: P.O. Box 1896, Georgetown, SC

29442

County: Georgetown

Previous Orders: None
Permit/ID Number: 1140-0039

Violations Cited: S.C. Code Ann. § 48-1-110(d)

Summary: Holcim (US) Inc. (Respondent) operates a Portland cement distribution terminal (cement unloading/loading operation) located at Pier 31 of the South Carolina State Ports Authority at Georgetown, South Carolina. The Respondent violated requirements of its permit as follows: failure to record pressure drop readings for its baghouse; failure to notify the Waccamaw EQC District Office as soon as the date of arrival for each marine vessel had been confirmed; commencement of cement unloading/loading operations prior to contacting the Waccamaw EQC District Office; and failure to provide notification to the Waccamaw EQC District Office at least 24 hours prior to commencement of cement unloading/loading of each marine vessel.

Action: Respondent has agreed to: record pressure drop readings for its baghouses; notify the Waccamaw EQC District Office as soon as the date of arrival for each marine vessel has been confirmed; not commence cement unloading/loading operations until the Waccamaw EQC District Office has been contacted; provide notification to the Waccamaw EQC District Office at least 24 hours prior to commencement of cement unloading/loading of each marine vessel; and pay a civil penalty in the amount of three thousand five hundred dollars (\$3,500.00). The penalty has been paid.

17) Order Type and Number: Consent Order 05-030-A

Order Date: June 20, 2005

Respondent: Trident Construction Co., Inc. of

Charleston

Facility: Trident Construction Co., Inc. of

Charleston

<u>Location/Mailing Address</u>: 2245 Technical Parkway

N. Charleston, South Carolina 29406

County: Dorchester

Previous Orders: 02-27-HW (\$4,350)

Permit/ID Number: N0503054

<u>Violations Cited</u>: U.S. EPA 40 CFR 61.145 (b),

Standard for Demolition and Renovation, and South Carolina Air Pollution Control Regulation 61-86.1, Section XIII.B.1.a, Standards For

Demolitions

<u>Summary</u>: Trident Construction Co., Inc. of Charleston (Respondent), located in N. Charleston, South Carolina, is a general contractor. The Respondent violated Federal and State asbestos regulations as follows: failed to provide written notification to the Department ten (10) working days prior to commencing demolition activities, and failed to obtain a demolition project license prior to commencing demolition activity.

Action: The Respondent has agreed to: submit all required notifications and obtain all required licenses prior to commencing demolition activity, in accordance with Federal and State asbestos regulations, and within thirty (30) days of the execution of this Order, pay to the Department a civil penalty in the amount of one thousand five hundred dollars (\$1,500.00). The penalty has been paid.